

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:

OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0070042
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, February 15, 2005
Start Date/Time:	2/15/2005 8:00:00 AM
End Date/Time:	2/15/2005 12:00:00 PM
Last Inspection:	Thursday, January 27, 2005

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Cloudy, Temp 30 Deg F
InspectionID Report Number: 533

Accepted by: pgrubaug 2/16/2005

Permitee: SUNNYSIDE COGENERATION ASSOCIATES
Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: STAR POINT REFUSE

Address: PO BOX 159, SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages Mineral Ownership Types of Operations

152.81	Total Permitted	☐ Federal	☐ Underground
88.78	Total Disturbed	☐ State	Surface
	Phase I	☐ County	Loadout
	Phase II	✓ Fee	Processing
	Phase III	Other	✓ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Pending actions: No pending actions.

Inspector's Signature

ate Wednesday, February 16, 2005

Karl Houskeeper, Environmental Scientist III Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Tuesday, February 15, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	o Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	✓		✓	

Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Tuesday, February 15, 2005 Page 3 of 3

2. Signs and Markers

The mine ID signs are located at the contact points of the public road to the permit area and contains all of the appropriate information. All other signs and markers observed during the inspection were in compliance with the approved MRP.

4.a Hydrologic Balance: Diversions

The entire area is snow covered, including the diversions.

4.d Hydrologic Balance: Water Monitoring

Information for the fourth quarter of 2004 has been entered into the EDI website and uploaded.

7. Coal Mine Waste, Refuse Piles, Impoundments

Mining on top of the refuse pile was taking place during the inspection. The material is being excavated and placed into piles. The piles are then loaded into trucks and hauled to the power plant located in Sunnyside.

22. Other

The operator's representative was not present during the inspection. The operator was notified upon arrival of the inspector that the inspection was to take place for safety and liability purposes.